

6957. Abunda Beauty device. (F.D.C. No. 45937. S. No. 67-398 R.)

QUANTITY: 5 individually ctn'd. devices at Lubbock, Tex.

SHIPPED: During July and August 1960, from San Mateo, Calif., by Abunda Products.

LABEL IN PART: (Ctn.) "Abunda Beauty by Abunda Products 20 Forty First Avenue-San Mateo, California" and (carrying case) "Abunda Beauty."

ACCOMPANYING LABELING: Booklets entitled "Abunda Beauty . . . a lovelier you"; leaflets entitled "Abunda Hydro Massage Bosom Beauty" and "Abunda Beauty * * * A New World of Loveliness"; and a number of carrying cases.

RESULTS OF INVESTIGATION: Photographs and labeling indicated the article to be a plastic cup-shaped device with a water hose attachment. In use, the cup was intended to be placed over the female breast with the hose attachment connected to the household water service. The water was caused to be diffused or "swirled" in passing through a perforated disc in the cup base. The swirling water within the cup reportedly served to massage the bust.

LIBELED: 7-5-61, N. Dist. Tex.

CHARGE: 502(a)—when shipped, the name of the article "Abunda Beauty," and its labeling contained false and misleading representations that the article was adequate and effective for awakening and increasing bosom beauty; encouraging bosom perfection; restoring, healing, and revitalizing the tissues of the bosom; increasing circulation of the bust; providing cell nourishment to firm the tissues; and for providing an abundant bust through hydrotherapy.

DISPOSITION: 11-17-61. Default—destruction.

6958. Magnetic bracelets. (F.D.C. No. 46525. S. No. 19-216 T.)

QUANTITY: 311 bracelets at Brownsville, Tex.

SHIPPED: 8-25-61 and 9-6-61, from New York, N.Y., by Patricia Watch Band Co.

LABEL IN PART: "Made in Japan Super Health."

RESULTS OF INVESTIGATION: Examination showed the article to be an aluminum expansion wristband fitted with a magnetic aid, having a gold top and stainless steel back.

LIBELED: On or about 11-8-61, S. Dist. Tex.

CHARGE: 502(a)—when shipped, the label statement "Super Health" was false and misleading since it suggested and implied that the article was adequate and effective for therapeutic uses whereas the article was of no value for any therapeutic use; and 502(b) (1)—the article failed to bear a label containing the name and place of business of the manufacturer, packer, or distributor.

DISPOSITION: 12-22-61 and 1-2-62. Default—50 bracelets delivered to the Food and Drug Administration and the remainder destroyed.

6959. Oxygen inhaler. (F.D.C. No. 46927. S. No. 39-087 T.)

QUANTITY: 61 ctns., 24 retail boxes each; 6 ctns.; 15 boxes, 10 cylinders each; and 300 cylinder holders, at New York, N.Y., in possession of Val-U-Air Products, Inc.

SHIPPED: Between 8-9-61 and 11-9-61, from Bloomfield and West Paterson, N.J.

LABEL IN PART: (Retail box) "Oxygen Air-Aid Inhaler & Cartridge Breathe oxygen to relieve: * * * cartridge contains approx. 3 qts. oxygen U.S.P. * * *